Licensed Asbestos Supervisor Framework CSCS Card Journey

Standard-Setting Body:

CITB - S/NVQ Standard

Sector Rep Org:
ACAD, ARCA

Competent Person Schemes:
N/A

Supervisor card

ACAD/ARCA validate achievement of S/NVQ, CCNSG Safety Passport or CITB HS&E Supervisor test pass, and if required, Fire Safety. A renewable Gold Supervisor card is issued, valid for 5 years.

Renewal requires:
S/NVQ Certificate, Supervisor Refresher Certificate, Fire Safety (TBC), and CITB HS&E Test for Supervisor or CCNSG Safety Passport.

Renewal after 5 years
1. Employer endorsement
2. Evidence of CPD (Soft Launch July 2025)
3. Continuing Professional Development (CPD) in Higher-Risk Building (HRB), if required
4. CITB HS&E and Fire Safety (July 2025)

All validated by ACAD/ARCA before renewal.

Assumptions

1 S/NVQ Level 2 and/or Level 3 remains occupation standard set by SROs & SSB
2 All relevant SROs engaged in development of SKEB
3 CITB (SSB) verify and update NOS to reflect SKEB
4 Awarding organisations and training providers update qualifications and training programmes to reflect SKEB
5 Relevant CSCS Alliance schemes issues cards based on the qualification & competency thresholds as agreed by SROs and SSB.

Supervisor Refresher Training Certificate (completed in previous 12 month).

CITB HS&E Test for Supervisor (in previous 2 years) or CCNSG Safety Passport.

Complete S/NVQ

Trained Supervisor card
ACAD/ARCA validate proof of training, Fire Safety (TBC), achievement of CITB HS&E test (Supervisory) or CCNSG Safety Passport and issue card.

New or Refresher Supervisor Training Certificate (completed in previous 12 month).

CITB Health Safety and Environment test for Supervisor (in the previous 2 years) or CCNSG Safety Passport.

Fire Safety (TBC).

New Entrant

Supervisor Refresher Training Certificate (completed in previous 12 month).

CITB HS&E Test for Supervisor (in previous 2 years) or CCNSG Safety Passport.

Complete S/NVQ

Experienced Supervisor card
ACAD/ARCA validate S/NVQ registration, Fire Safety (TBC), CCNSG Safety Passport or CITB HSE (Supervisory) test pass, and issue card.

Registered and actively undertaking the L2 S/NVQ in Removal of Hazardous Waste (with ACAD/ARCA or another provider) AND Registered on L3 NVQ Diploma in Occupational Work Supervision OR Hold L2 S/NVQ in Removal of Hazardous Waste AND Registered on L3 NVQ Diploma in Occupational Work Supervision

Supervisor Refresher Training Certificate (completed in previous 12 month).

CITB Health Safety and Environment test for Supervisor (in the previous 2 years) or CCNSG Safety Passport.

Fire Safety (TBC).

Experienced Worker Route

The Labourer card is not a recognised training pathway. Where appropriate workers should be encouraged to follow a Red Card route.

Obtain **Green Labourer card.**
This card is valid for 2 years and is renewable.
Renewal requires:
1 Retake the CITB Health, Safety and Environmental test
2 Retake the CITB Safety training (assumption)

Content of qualifications below to be agreed between SROs and SSB

Pass one of the following:
1 The Level 1 (Scotland Level 4) Award in Health and Safety in a Construction Environment
2 The Scottish Level 5 REHIS Elementary Health and Safety Certificate
3 The NOCN/CSkills Awards Construction Health and Safety (F/618/0738) unit
4 CSCS approved alternative qualification

CITB Health Safety and Environment test.
Content agreed between SROs & SSB

CITB Fire Safety in Buildings.

Labourer Route

Skilled Pathways as set by ACAD, ARCA and CSCS

Unskilled Pathways as set by SROs and SSB